




HP50A

HEAT PUMP REPLACEMENT PARTS

Parts Listing: HP50A



Ref. No.	Part No.	Description
1	HPX32012-120020	Evaporator
2	HPX20000-220188	Fan Net
3	HPX3404-3301	Fan Motor
4	HPX3500-2701	Axis blower Fan
5	HPX2004-1437	4-Way Valve
6	HPX20000-110041	Compressor
7	HPX20000-360005	Water Flow Switch
8	HPX32008-120008	Titanium Tube Heat Exchanger
9	HPX3400-2203	Drain Plug
10	HPX2001-3605	High Pressure Switch
11	HPX32012-220044	Front Panel
12	HPX35012-22001	Cover
13	HPX2001-3907	Terminal Block 5
14	HPCxPAN1930	Waterproof Cover
15	HPX2000-3501	Fan Capacitor 30uF / 450 VAC
16	HPXLCD50	LCD Controller
17	HPXMCB50	Main Control Board
18	HPX2000-3603	Low Pressure Switch
19	HPX2000-3505	Compressor Capacitor 50uF / 450 VAC
20	HPX20000-360006	AC Contactor
21	HPX20000-140153	Needle Valve
22	HPX2000-3242	Sensor, water, air
23	HPX200-1402	Electronic Expansion Valve
	HPX200-3909	Terminal Block 2
	HPX20000-370003	Transformer